

**Hydrologic Unit Code**

10030203

**Watershed**

MARIAS

ID	Segment ID	Waterbody Segment	List Category	Size	Use Class	Use Support						Probable Causes of Impairment	Probable Sources of Impairment	
						Aqua Life	Cold Fish	Warm Fish	Drink Water	Swim (Rec)	Agri	Ind		
1	MT41P001_021	MARIAS RIVER Tiber Dam to Co Road X-ing in T29N,R6E,Sec17	4C	10.8 M	B-1	P	P	P	X	F	F	F	Flow alteration Other habitat alterations	Flow Regulation/Modification Hydromodification Agriculture Grazing related Sources Habitat Modification (other than Hydromodification) Removal of Riparian Vegetation
2	MT41P001_022	MARIAS RIVER from Co road x-ing in T29N,R6E,Sec 17 to mouth (Missouri R)	4C	70.89 M	B-2	P		P	X	F	F	F	Flow alteration	Flow Regulation/Modification Hydromodification
3	MT41P002_030	PONDERA CREEK/COULEE, Headwaters to the mouth (Marias R)	5	118.5 M	B-2	P	P		X	X	X	X	Salinity/TDS/sulfates Bank erosion Riparian degradation Other habitat alterations	Crop-related Sources Grazing related Sources Agriculture
4	MT41P002_050	CORRAL CREEK, Headwaters to mouth at Government-Cottonwood Crs	5	19.2 M	B-2	P	P		X	X	X	X	Nutrients	Crop-related Sources Agriculture

F = Full Support   P = Partial Support   T = Threatened   N = Not Supported   X = Not Assessed